

# **What's New in Topside Paint?**



**Surface Navy Association, Arlington, VA**

**Jan. 2013**

**Mr. Mark Ingle, P.E.**

**Technical Warrant Holder, Coatings and Corrosion Control**

**(202) 781-3665**


**[mark.w.ingle@navy.mil](mailto:mark.w.ingle@navy.mil)**

# Introduction

- Brief background and history of Navy surface-ship topside coatings.
- NAVSEA success with improving color stability, durability, and service life of topside paints.
- Surface Fleet opportunities for reducing total ownership cost of surface-ship topside coatings.



# Naval Systems Engineering Directorate (SEA 05)



SEA 05PB - Deputy  
SEA 05P2 - Materials  
Coatings & Corrosion  
Control  
Cathodic Protection  
Composites Materials  
Welding & Metals  
Non-destructive testing  
Fuels and Lubricants

# Topside Coating History

- Navy topside coatings developed over decades:

- Sept. 1941 - Bureau of Ships includes "haze gray" color in palette for surface ship camouflage.

10) - 1943  
1952 - modern haze gray color adopted.



USS CONCORD (DD-714)

- June 1963 - NAVSHIPS report concludes semi-gloss

"haze gray" color is best:  
*"from pole to pole, all seasons,  
around the clock."*

- Color intended to conceal ship against background sea & sky.
    - Mast and stacks black to hide soot.
    - Numbers white & black.



USS EDSON (DD-946) - 1974

- Sept. 1989 - NAVSEA report based on visual tests, interviews, and photographs showed benefits of reduced contrast by entire topside being haze gray, light gray and ocean gray.




USS JASON DUNHAM (DDG-105)

- Sept. 1992 - NAVSEA "Camouflage Manual for Surface Ship Concealment" published

2010  
Distribution Statement A: Approved for public release; distribution is unlimited.  
and requires haze gray and counter-shading.

# The Evolution of Low Solar Absorbance Topcoat Coatings

- Low solar absorbance (LSA) topcoats developed by Naval Research Laboratory (NRL) in late 1990s to reduce heat load on DD-963s operating in Persian Gulf. June, 2000 first LSA paint installed on ex-USS FLETCHER (DD-992). LSA pigments are a **commercial, business.**
- LSA topcoat applied to entire freeboard and superstructure. NRL measured 6°F reduction in surface temperature on DD-963s. DD-963s operated in Persian Gulf without expensive air-conditioning plant upgrade.
- LSA coatings on lower portion of LCS-1 superstructure compared with uncoated





**LSA paint required since 2002, reducing ship energy consumption when air conditioning operational**

# So Why Do LSA Paints Fade?


**PROBLEM: First Generation LSA paints are color shifting in Florida.**

- **LSA topcoats developed in late 1990s entered a world in which over-coating paint was common.**
  - Crew over-coating common.
  - Ships docked 3-5 years and were repainted.
  - 41 coats of paint on some areas of 49 year old ship.
- **Topside coating military specification, MIL-PRF-24635B (1995) required color & gloss testing:**
  - One year, Florida, 45°-south.
  - 60° Gloss not less than 50% of original.
  - CIE color values as per ASTM-D-2244  
delta E shall be not greater than 1.0 CIELAB unit


delta E >4 easy to perceive - <1 hard to perceive



Non-LSA Pigment



# Solutions to Fading Paint in Place



Dec. 2010 NAVSEA Naval Message 131732Z Dec 10 provides paint procurement guidance to Fleet:

Type II - NO LONGER AUTHORIZED - USE UP STOCK

Type III - RECOMMENDED

Type V - RECOMMENDED with EXTREMELY HIGH FADE RESISTANCE

Universal paint requirements document, FY-12, Change 1, Standard Item 009-32 includes process

for installing polysiloxane coating - only allows use of BETTER or BEST.

- NSWC-SSES Naval Message 131500Z SEP 12 describes processes for repairing polysiloxane and over-coating existing paint - all ships in fleet can use BEST paint.

Distribution Statement A:  
Approved for public release; distribution is unlimited.

Must be careful because polysiloxane is two-part paint that requires mixing.  
**NAVSEA has solution in place to resolve topside fading issue**

# Long-term Ship Tests Prove Concept

- First LSA demonstration, USS PONCE (LPD-5) in 2006.
- Data collection on USS KEARSARGE (LHD-3) signal shack install from MAY 2008. Color shift in excess of 1 Delta E.



Approximate color shift of  
Type II alkyd (red)

Delta E


>6



Approximate color shift of  
Type V polysiloxane (blue)

Delta E

>2.05





Polysiloxane on USS KEARSARGE (LHD-3) exhibited Color Shift - difficult to perceive

Distribution Statement A: Approved for public release; distribution is unlimited.


# Reducing Probability of topside Coating Failure

- NAVSEA defined “failure” of a topside paint as when color obviously faded Delta E = 4.6 is “failure” based on color measurement instrument vector math.
- Panel & ship data measured quarterly (as available).
  - Silicone alkyds show a high probability of failing between 2 and 3 years
  - Polysiloxanes show negligible probability of unacceptable color shift to date.



# Polysiloxane Use Expanding In Fleet

Polysiloxane Installations by Year



**Ships want the polysiloxane coatings and NAVSEA Corrosion Control Assistance Teams support Fleet**

# Polysiloxane is Reducing Install & Total Ownership Costs

- Polysiloxane is a premium-priced paint, but durable and color stable. Coating provides both corrosion-control and topside functionality.
- FY-12, Change 1, Standard Item 009-32 requires polysiloxane coating application with one fewer coat than alkyd.

Silicone Alkyd  
Epoxy Primer



Epoxy Stripe Coat

Epoxy Primer

Silicone Alkyd Topcoat

Polysiloxane  
Epoxy Primer

Epoxy or Polysiloxane Stripe Coat

Polysiloxane Topcoat



- Business case developed based on coating 310,000 square foot LHD topside.  
materials, & labor:

	<u>Silicone Alkyd</u>	<u>Polysiloxane</u>
Paint Material Cost	\$160,580	\$212,350 (less epoxy, thicker film)
Labor & QA	<u>\$569,625</u>	<u>\$325,500</u>
TOTAL ESTIMATED JOB COSTS	<b>\$730,205</b>	<b>\$537,850</b>

# What can Fleet Do to Reduce Maintenance Costs?

- NAVSEA needs fleet help to change the model for topside maintenance.
  - Clean the ship (like your car).
  - Don't repaint the ship (like your house).

Sailor and Bosun's Mate provided positive feedback on ease of cleaning



Cleaning success on:  
CVN-71  
DDG-79  
LHD-1  
LSD-41

- SEA 21 is developing Lead Ship Initiative to get all new coatings & corrosion-control technology, including polysiloxane, on one ship to demonstrate savings
- We need to avoid repainting. Nov. 2012 inquiry from supply officer on ship recently coated with polysiloxane requested source for a polyurethane alkyd paint to overcoat.



Polysiloxane coating applied to ship in 2010




Multiple areas under catwalk over-coated with alkyd by 2012.

Distribution Statement A  
Approved for public release; distribution is unlimited.

# Backup slides

# Paint Application Process Control is Key

- Installations of polysiloxane show 93% success rate Number of Jobs with **two partial failures**.
  - One on each coast.
  - Local portion of overall job >90% of coating adherent, small areas delaminating.
- Failure analysis:
  - Surface cleanliness is key. **Polysiloxane is not surface tolerant.**
  - Application must follow requirements in Standard Item 009-32.
  - Overcoat window is key. SEA 05P2 directed all suppliers to ensure ASTM-F-718s included details to preclude failure.



■ Demonstration  
■ Topside  
■ Partial Delamination

# Future Reductions in Total Ownership Costs

- Candidates for future success in NAVSEA coatings and processes to reduce total ownership costs:
- SEA 05 New Construction Working Group shifting good ideas from maintenance to new construction:
  - “Top Nine” ideas approved by NAVSEA already.
  - Leverage good ideas from NAVSEA, Standard Item 009-32, and industry into contractual changes.  
**Plan is to produce actual contract changes.**



- Developing high-solids, MIL-DTL-24441 to go from five coats to one:
  - One vendor's candidate product passed cathodic disbondment testing.
  - Resolving cracking and overcoat issues.  
**Plan is to significantly reduce steps in tank coating.**



- Coordinating with Cumbersome Work Practices, Paint Center of Excellence, National Shipbuilding Research Program, and others to generate successes.
  - Extend retention of preconstruction primer to single-coat paint.
  - Streamline coating quality assurance process.  
**Plan is to focus all efforts on value-added processes.**